

ASSEMBLY INSTRUCTION

HK-US3007


Ax1



Bx2




Cx1




Dx1




Ex1




Fx1



1









Wait 72 hours for rebound


2



3




4



Insert parts(D)into the marked position.

5



6

