

TEST REPORT

APPLICANT : SHOUGUANG DASEN WOOD CO.,LTD

ADDRESS : No.10,Xingfu Street,Houzhen,Shouguang,Shandong province,China

SAMPLE DESCRIPTION : FURNITURE

ITEM NO. : 831-337

COUNTRY OF ORIGIN : China

COUNTRY OF DESTINATION : Canada,France,UK,Germany,Spain,Italy

SAMPLE RECEIVED DATE : 06-Sep-2022

FURTHER INFORMATION DATE : 14-Sep-2022

TURN AROUND TIME : 06-Sep-2022 to 16-Sep-2022

REVISED DATE : 11-Nov-2022

The following test item(s) was/were performed on submitted sample(s) and/or component(s) confirmed by applicant

TEST REQUESTED	TEST METHOD/REGULATION	RESULT
Total Lead and Mercury in Surface Coating	SOR/2016-193, Surface Coating Materials Regulations	Pass
Total Mercury Content	SOR/2014-254, Products Containing Mercury Regulations	Pass
Safety for Clothing Storage Units	ASTM F2057-19	Pass

Remark:

This report cancels and supersedes report number EFHZ22090345-CG-01 issued on Sep 16, 2022. Modification description: per client's request, add Total Mercury Content test for component No.1 in the revised report.

Eurofins (Hangzhou) contact information


Customer service: ConnieZhang2@eurofins.com/ +86 571 87203730

Sales specialist: SammyDong@eurofins.com/ +86 571 87203730

***** FOR FURTHER DETAILS, PLEASE REFER TO THE FOLLOWING PAGE(S) *****

Signed for and on behalf of

Eurofins Product Testing Service (Shanghai) Co., Ltd. Hangzhou Branch



Sara Liu
Lab Manager

Samples are obtained by express delivery, Results obtained refer only to samples, products or material received in Laboratory, as described in point related to sample description, and tested in conditions shown in present report. Eurofins Product Testing Service (Shanghai) Co., Ltd ensures that this job has been performed according to our Quality System and complying contract and legal conditions. If you happen to have any comments, please do it by sending email to info.hz@eurofins.com and referring to this report number. Reproduction of this document is only valid if it is done completely and under the written permission of Eurofins Product Testing Service (Shanghai) Co., Ltd. If you happen to have any complaints, please do it by sending email to chinacomplaint@eurofins.com and referring to this report number.

SAMPLE PHOTO(S)**A****EFHZ22090345-CG-01+Rev1**

COMPONENT LIST

Component No.	Component	Sample No.
1	White coating on wood	A

TO BE CONTINUED

TEST RESULT

Total Lead and Mercury in Surface Coating

Test Request: Total lead and mercury in surface coatings as specified in Canada Consumer Product Safety Act, Surface Coating Materials Regulations, SOR/2016-193

Test Method: With reference to Canada Health Product Safety Bureau, Reference Manual Book 5 - Laboratory Policies and Procedures, Part B: Test Methods Section, Method C02.2.1-2021, Method C07-2019(modified)

Test Item(s)	Unit	Limit	MDL	Result
				1
Total Mercury	mg/kg	10	1	ND
Total Lead	mg/kg	90	10	ND

Remark:

mg/kg = milligram per kilogram

MDL = method detection limit

ND = Not detected, less than MDL

Total Mercury Content

Test Request: Total mercury Content as specified in SOR/2014-254, Products Containing Mercury Regulations

Test Method: Acid digestion method, analysis was performed by ICP-OES

Test Item(s)	Unit	Limit	MDL	Result
				1
Mercury (Hg)	%	See Remark	0.0001	ND

Remark:

(1) Product (other than a battery), 0.1% or less by weight in homogeneous materials

(2) Battery, 0.0005% or less by weight in homogeneous materials

1 mg/kg = 1 ppm = 0.0001%

MDL = method detection limit

ND = Not detected, less than MDL

TO BE CONTINUED

TEST RESULT

Refer to ASTM F2057-19 Standard Safety Specification for Clothing Storage Units (As per client's request)

1. Number of tested samples: 1 Piece
2. Test result:

Clause	Test Method / Requirement	Result
4	Performance Requirements	
4.1	With the unit empty and without the tipover restraint, test the unit in accordance with 7.1 and 7.2	Pass
4.2	During the test, the unit shall not tip over or be supported by any component unless that component was specifically designed for that purpose	Pass
4.3	If a failed component prohibits the completion of the test, then the failed components shall be repaired or replaced to the original specifications, or the component replaced and the test repeated with the failed component secured as to not affect the test results but to prevent the component from failing	N/A
4.4	Tipover restraints shall be included with each item of furniture covered under the scope of this safety specification for attachment by the consumer.	Pass
4.5	The tipver restraint provided shall meet the requirement specification F 3096	Pass
8	Marking and labelling	Pass*

Note: N/A=Not applicable

*:means that only artwork with required information was provided.

END OF THE REPORT