



Total Quality. Assured.

Report No. 220627020GZU-001

Testing Laboratory: Intertek Testing Services Shenzhen Ltd. Guangzhou Branch
Address: Room101/301/401/102/202/302/402/502/602/702/802, No.7-2, Caipin Road, Huangpu District, Guangzhou, Guangdong, China

Applicant: JINHUAN Electrical Co.,Ltd
Address: Building B, No. 13, 1st Industry Zone, Hecheng Town, Heshan, Jiangmen, Guangdong, China

Manufacturing site: Same as Applicant
Address: Same as Applicant Address
Testing Location: Same as Testing Laboratory
Address: Same as Testing Laboratory Address
Product: Clothes Dryer
Brand Name: HOMCOM

Description: The product covered by this report is a household, indoor use, fix connected clothes dryer.

Model(s): B61-009V80CG; B61-009V80WT

Model Similarity: All Models are identical except for the appearance and the model name.

Ratings: 120V,60Hz,850W
Date of receipt of sample(s): 28-Jun-2022
Date Range of Test: 14-Jul-2022
Test standard(s) or criteria(s): 10 CFR Appendix D1 to Subpart B of Part 430—Uniform Test Method for Measuring the Energy Consumption of Clothes Dryers

California Code of Regulations, Title 20, Division 2, Chapter 4, Article 4, Sections 1601-1609: Appliance Efficiency Regulations

Conclusion: These results are in compliance with requirements of DOE and CEC.

Prepared by: Elvis Cai
Title: Engineer

Approved by: Felix Li
Title: Technical Supervisor

Signature: Elvis Cai

Signature: Felix Li

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program. Determination of the test conclusion is based on IEC Guide 115 in consideration of measurement uncertainty.