



# ASSEMBLY INSTRUCTION

H08-RZ-DE3001L

Ax1




①




Wait 72 hours for rebound


③




Cx1




②



④




Dx1



# MONTAGEANLEITUNG


H08-RZ-DE3001L

Ax1




①

WDas linke gerüst




Warten sie auf den nächsten  
72 stunden


③




Cx1




②



④




Dx1



# INSTRUCTION DASSEMBLAG


H08-RZ-DE3001L

Ax1




①


Cadre du siège gauche



③




Cx1




Attendre 72 heures pour le rebond


②



④




Dx1



# ISTRUZIONI DI ASSEMBLAGGIO


H08-RZ-DE3001L

Ax1




①


Telaio del sedile sinistro



③



Cx1






②

Aspetta 72 ore per il contraccollo

④


Dx1



# INSTRUCCIÓN DEMONTAJE


H08-RZ-DE3001L

Ax1




①


Marco del asiento izquierdo



③




Cx1




Esperar 72 horas para el rebote

②



④



Dx1

